

Mint of the United States at Philadelphia, Pa.,

SUPERINTENDENT'S OFFICE,

April 7 - , 1885.

Sir

I have the honor to report the following as the result of a careful examination of the large balance in use in the transfer room. I find that after 9 years of constant use it should be sent to the original manufacturer for general and thorough repairs, and new working parts supplied such as bearings pivots and all other parts affected by friction with new alignments of the beam and its hangings so as to give the balance a higher sensibility and regularity of swing. In order to make these needed repairs it would be best in my opinion to have the old balance formerly used in the Weighing Room

2
 put in perfect order by supplying such new parts as are necessary, inasmuch as said balance is far better suited for the work done in the Coining Room than the light balance now in use as it has always given great trouble and anxiety to keep its weighing qualities up to the standard due to the fact that it is entirely too light for the work required of it.

I respectfully suggest that the above changes be made which will remedy all trouble in the future between the General and Coining Departments and give the Institution two first class balances suitable for the heavy work required of them.

Wm. C. London Snowden

Supt. U. S. Mint

Very respectfully

Ellis Tugh

Director of scales

328 1/2

Mint of the United States at Philadelphia, Pa.,

SUPERINTENDENT'S OFFICE,

April 7th 1885.
 Ellis Pugh Adjuster of Scales
Superintendent.

Suggests that the large
 Balance in use in the
 transfer room should be
 sent to the Original Man-
 ufacture for repairs -

No. of Enclosures.



[Abstract:] Suggests that the large Balance in use in the transfer room should be sent...

Mint of the United States at Philadelphia, Pa.,
Superintendent's Office,
April 7, 1885

Sir

I have the honor to report the following as the result of a careful examination of the large balance in use in the transfer room, I find that after 9 years of constant use it should be sent to the original manufacturer for general and thorough repairs, and new working parts supplied such as bearings pivots and all other parts affected by fiction with new alignments of the beam and its hangings so as to give the balance a higher sensibility and regularity of swing. In order to make these needed repairs it would be best in my opinion to have the old balance formerly used in the Coining Room put in perfect order by supplying such new parts as are necessary, inasmuch as said balance is far better suited for the work done in the Coining Room than the light balance now in use as it has always given great trouble and anxiety to keep its weighing qualities up to the Standard due to the fact that it is entirely too light for the work required of it.

I respectfully suggest that the above changes be made which will remedy all trouble in the future between the General and Coining Departments and give the Institution two first-class balances suitable for the heavy work required of them.

Very respectfully,
Ellis Pugh
Adjuster of Scales

Hon. Loudon Snowden
Supt. U.S. Mint